

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,942,445 B2

APPLICATION NO.: 10/729,695

ISSUE DATE : September 13, 2005

INVENTOR(S) : Morris et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, line 2, "600" should be changed to --60°--;  
Column 10, line 5, "600" should be changed to --60°--;  
Column 11, line 8, "600" should be changed to --60°--;  
Column 11, line 32, "200" should be changed to --20°--.

### MAILING ADDRESS OF SENDER (Please do not use customer number below):

Ingrassia Fisher & Lorenz  
7150 E. Camelback Rd., Suite 325  
Scottsdale, Arizona 85251

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

In re U. S. Patent: 6,942,445 B2

Examiner: N. H. Nguyen

Issued: September 13, 2005

Group: 3745

Inventor(s): Morris et al.

Docket No. H0005707

For: GAS TURBINE COOLED SHROUD ASSEMBLY WITH HOT GAS INGESTION  
SUPPRESSION

**CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322**

Attn: Certificate of Corrections Branch  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for a Patent Office mistake under Rule 1.322 as follows:

Column 10, line 2, "600" should be changed to --60°--;

Column 10, line 5, "600" should be changed to --60°--;

Column 11, line 8, "600" should be changed to --60°--;

Column 11, line 32, "200" should be changed to --20°--.

These errors occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: February 6, 2007  
Ingrassia Fisher & Lorenz, P.C.

/PAUL D. AMROZOWICZ/  
By: Paul D. Amrozowicz  
Attorney for Applicant(s)  
Reg. No. 45,264  
Tel. (480) 385-5060